

PENNSYLVANIA STATE MINING REPORTS

**BERWIND-WHITE COAL MINING COMPANY'S MINES IN THE WINDBER AREA:
FATAL ACCIDENTS, 1897-1918**

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1897 June 14	LIPKO, JOE	Miner	24	Yellow Run Shaft, Dunlo	Cambria	Killed by a fall of coal.
1898 Feb. 9	LULLY, ANDY	Spragger on motor	23	Single	Eureka No. 30	Somerset	This young man was running past his motor to turn a switch and he fell before the motor and was run over; he jumped off the motor on the wrong side, which necessitated his crossing the track ahead of the motor to reach the switch, so when he fell he was caught as stated.
1898 April 15	EDMUSTON, DAVID E.	Laborer	18	Single	Eureka No. 33	Somerset	This man was killed by a large fall of rock in the shape of a large pot or boiler, a very dangerous piece of rock in mines; this piece of rock had been tested by mine foreman less than an hour before it fell, and sounded solid; this was an unavoidable accident.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1898 May 7	COIRGIN, REUBEN	Spragger on motor	18	Single	Eureka No. 30	Somerset	It was difficult to tell what caused the death of this young man; it was claimed that he complained in the morning of pain in his stomach and during this morning the motor upon which he worked was hauling some large timber into the mine and the timbers became moved out of position and they stopped the trip to straighten them up. The motorman was at one end of timber which was possibly twenty feet long and this young man at the other, and in moving timber which was direct under the trolley wire, he gave one groan and fell over dead. Whether he touched the wire or not is a question; the doctor claimed that body showed no indications of death by electricity and he thought it might have been heart trouble.
1898 June 4	KOSSTYO, MIKE	Laborer	20	Single	Eureka No. 30	Somerset	Was pushing a car and standing in water, and the back of his neck touched the trolley wire which killed him instantly.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1898 July 8	SAMBOL, MIKE	Miner	35	Married	2	...	Yellow Run Shaft, Dunlo	Cambria	Was killed by a fall of roof, which a good practical miner would have propped and made it secure.
1898 July 27	HARCHICK, JOHN	Miner	30	Married	4	...	Eureka No. 30	Somerset	This man was killed by a fall of rock, there were two others with him who barely escaped the same fate; it was a very treacherous piece of top, and the foreman had just tested it and it seemed safe and solid.
1898 Nov. 29	DYKE, MIKE	Miner	43	Married	2	...	Eureka No. 31	Somerset	Skull crushed by a fall of coal for lack of it being sprigged.
1899 Jan. 21	KOBAL, JOHN	Loader	40	Married	4	...	Eureka No. 32	Somerset	Killed by electricity. He ran his car out across the main heading track, and when under the trolley wire he stood up and struck the back of his head against the naked wire. He had been sick with the grip for a couple of weeks, and this was his first day to work, therefore was in a bad condition to stand the shock.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1899 Mar. 1	HOLIGAN, MICHAEL	Rock man	40	Single	Eureka No. 32	Somerset	Crushed under large piece of rock. He was barring it down, his bar slipped, which threw him just as it was falling and it caught him on the back of the head, and killed him instantly.
1899 June 7	MUDOCK, STEVE	Loader	29	Married	2	...	Eureka No. 30	Somerset	Killed by electricity. He was pushing a car on to face of heading where he was working, and was standing at time he touched his head against the wire.
1899 June 26	FOREMAN, ROBERT	Trackman	26	Single	Eureka No. 32	Somerset	Killed by electricity. He was working in one of the cross headings pulling up an old switch, and being a long time at the job, one of the men went to look for him and found him lying dead; his work was done, and it was supposed that he was rising up to leave when some of the tools on his back touched the wire.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1899 Nov. 14	IGLETSKI, JACOB	Loader	35	Single	Eureka No. 31	Somerset	This man came in contact with the trolley wire; he turned to the side to get out of the way of the motor, and went on the side the trolley wire was on, instead of the other side where there was a width of over 3 feet from rail to rib.
1899 Nov. 16	[ADAMCIK] ADAMICK, PETER	Loader	21	Eureka No. 31	Somerset	Killed by a car striking him on the stomach. He was working in a heading which was going to the dip heavily, and while the motor was pulling cars out he was instructed by his foreman to get into the cross-cut until cars were pulled over the summit, but this time at least he did not, and a coupling broke and let a car down, which struck the one he was loading, and it struck him on the stomach and killed him.
1899 Dec. 2	AUBRY, THOMAS	Trapper	13	Single	Eureka No. 30	Somerset	This boy jumped on the front end of a trip of empty cars that was being pushed into the heading, and they jumped the track, and crushed his leg so that it had to be amputated, and he died in about one hour and a half after.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1900 Jan. 5	DARBY, EDWARD	Electrician	31	Single	...	American	Eureka No. 30	Somerset	Killed by electric shock; in making some repairs to wire in the mine he came in contact with the trolley wire and was instantly killed.
1900 Feb. 5	GORDON, JOHN	Miner	18	Single	...	Slav	Yellow Run Shaft, Dunlo	Cambria	Killed by fall of coal which he neglected to sprag.
1900 Feb. 8	HOWAT, PHILIP	Miner	28	Single	...	Slav	Yellow Run Shaft, Dunlo	Cambria	Fatally injured by a fall of draw slate from the side of the heading; an unavoidable accident.
1900 April 2	ANDREW, JAMES	Miner	40	Married	1	Slav	Eureka No. 31	Somerset	Fatally injured by fall of coal owing to his carelessness in not spragging it.
1900 May 16	KIBBLING, WILLIAM	Miner	54	Married	3	English	Eureka No. 31	Somerset	Fatally injured by a fall of draw slate; was drawing a pillar and the place was squeezing and crushed the draw slate around the prop, causing it to fall on him.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1900 June 21	BALASCOCK, JOSEPH	Track man	21	Single	...	Hungarian	Eureka No. 32	Somerset	Killed by electric shock; was warned by his partner to look out for the wire, but pushed his head against it.
1900 July 23`	BASSOCK, JOHN	Laborer	26	Single	...	Slav	Eureka No. 33	Somerset	Killed by electric shock; was walking on heading with an iron bar on his shoulder and it touched the trolley wire.
1900 July 31	HUNTER, JOHN	Loader	13	Single	...	American	Eureka No. 34	Somerset	Was run over by motor while on his way home out of mine. The road is double and he stepped out from in front of empty trip right in front of full load and was run over.
1900 Sept. 8	FELDEN, MARTIN	Loader	40	Married	8	Hungarian	Eureka No. 30	Somerset	Coming out of the mine he stepped in front of a motor; he had no light in his lamp, therefore could not be seen by motorman.
1900 Sept. 24	COMENTICK, MIKE	Miner	36	Married	1	Slav	Eureka No. 36	Somerset	Fatally injured by a fall of rock in a heading; accident was unavoidable.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1901 Jan. 4	BARRON, MIKE	Loader	36	Married	2	Austrian	Eureka No. 35	Somerset	Was badly crushed; he was sitting in his room and the empty cars being pushed by motor caught him between cars and rib.
1901 Feb. 16	HERSHSTOCK, ANDY	Loader	32	Married	1	Austrian	Eureka No. 35	Somerset	Was running a coal car out of the room and struck his head against trolley wire.
1901 Mar. 26	THURSTON, SARUS	Miner	33	Married	4	Norwegian	Eureka No. 30	Somerset	Was found dead on the road under trolley wire.
1901 May 6	COMESKIE, JOHN	Miner	25	Single	...	Slav	Eureka No. 35	Somerset	Fatally injured by a fall of coal. He had left a stump of coal to hold the coal up and lay down under the cut of coal to mine out the stump.
1901 May 11	POSTLEMICK, VALENTINE	Road cleaner	43	Married	4	Austrian	Eureka No. 30	Somerset	Run over by electric motor. He was not on the lookout for motor, and was told to get off the track, but did not.
1901 May 27	ODER, JAMES	Miner	42	Married	4	Pole	Eureka No. 36	Somerset	Ran his car on the heading to load coal that was not on the road and fell, his head striking the rail; when picked up he was dead; no marks were found on him only where his head struck the rail. The electric wire was right above him.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1901 June 18	STILMAN, ANDY	Miner	24	Single	...	Pole	Eureka No. 33	Somerset	Coming out of the mine and was struck by a motor.
1902 Jan. 8	PINZELMIS, MIKE	Miner	54	Married	3	Austrian	Eureka No. 30	Somerset	Killed by electric shock; this man, with other, was drawing heading stumps; there was a piece of bad rock which they were pulling down, and he jumped back out of road of the falling rock and struck the back of his head against the trolley wire, which caused his death.
1902 Feb. 27	ZACK, ANTON	Loader	36	Married	3	Polish	Eureka No. 34	Somerset	This man had pushed his car out of the room and it stopped on the switch, and he went around on the wire side to pull out a sprag, when he struck his head against the trolley wire, which killed him.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1902 April 19	MONDAY, JOSEPH	Loader	34	Single	...	Polish	Eureka No. 37	Cambria	This man was killed by electric wire while lifting a car on the track with a rail for a lever, which slipped and threw him against the electric wire, causing his death from electric shock.
1902 June 11	METARKO, PETER	Machine cutter	29	Married	3	Slovak	Eureka No. 33	Somerset	Neck broken by fall of coal and rock he was undermining, when a slip in the rock was reached and the rock and coal fell; accident was unavoidable.
1902 July 11	MORABIT, BARNO	Miner	28	Married	2	Italian	Eureka No. 34	Somerset	Killed by a fall of draw slate.
1902 July 15	SAVITCH, JOHN	Rock man	37	Married	...	Slovak	Eureka No. 34	Somerset	This man, with others, was blasting some sand rock; he went back to a box to prepare a piece of dynamite and in some unknown manner the piece exploded, which exploded the balance of the dynamite, causing a terrible explosion, blowing him to pieces.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1902 July 19	BANAL, JOHN	Miner	19	Single	...	Russian	Eureka No. 30	Somerset	Shocked to death by electricity; this man was on the road and the motor came along, and he turned out on the side where the wire was, instead of the other side, and while standing there he struck his head against the wire, which killed him.
1902 Aug. 9	BRESKO, GEORGE	Miner	29	Married	1	Polish	Eureka No. 35	Cambria	Killed by electricity; this man was walking along the road or rail, with his hand on the top; there was a small wire from the trolley wire into tool shanty and he took hold of it and it caused his death.
1902 Aug. 23	KUK, DEMICURE	Loader	26	Single	...	Hungarian	Eureka No. 37	Cambria	Was killed by a fall of rock; while drilling a hole in his coal, a piece of rock fell out of a pot hole in the roof; it was an unavoidable accident.
1902 Sept. 17	KESPERIUSKI, GEORGE	Loader	45	Married	5	Hungarian	Eureka No. 37	Cambria	Head crushed by a fall of rock; this was an unavoidable accident; two slips which came together in the roof and were not visible, caused the rock to fall, killing him instantly.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1902 Oct. 7	MOISISH, LOUIS	Miner	39	Married	1	Hungarian	Eureka No. 34	Somerset	Killed by a fall of coal; coal fell off a slip and struck him on the temple; it was a very small lump of coal, but it killed him instantly.
1902 Oct. 19	HAMMEL, EDWARD	Spragger	22	Single	...	American	Eureka No. 32	Somerset	Was spragging, and in going in on the motor he leaned back and his head struck a prop, which knocked him off and he was crushed to death.
1902 Dec. 4	DEMBROSKY, FRANK	Loader	20	Single	...	Polish	Eureka No. 31	Somerset	Killed by a fall of rock; Tapensky sat down beside Dembrosky, who was loading a car, when, suddenly, several tons of rock fell on both men, killing them; the place was well propped, but there was a clay vein on one side of the road; was an unavoidable accident.
1902 Dec. 4	TAPENSKY, ADAM	Scraper	29	Single	...	Polish	Eureka No. 31	Somerset	Killed by a fall of rock; Tapensky sat down beside Dembrosky, who was loading a car, when, suddenly, several tons of rock fell on both men, killing them; the place was well propped, but there was a clay vein on one side of the road; was an unavoidable accident.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1903 Jan. 6	GAHAGAN, JOHN	Miner	18	Single	...	American	Eureka No. 39	Somerset	Killed by fall of roof in his place or room. He had been cautioned twice that morning to set up some more props, but he did not heed the advice.
1903 Mar. 2	SHERISH, MARTIN	Miner	40	Married	...	Hungarian	Eureka No. 37	Cambria	Broken thigh. Died about three hours after accident, which was caused by a fall of rock while he was loading a car. Could have been avoided by careful propping of his place.
1903 Mar. 17	BORTMAN, FRANK	Spragger	20	Single	...	American	Eureka No. 31	Cambria	This man after unhitching the car from the motor jumped on the corner of his motor and was caught under the roof and squeezed to death. He knew there was not enough of height to ride on top of motor and therefore should not have jumped on.
1903 June 9	GLADVIA, MIKE	Miner	30	Married	...	Slavonian	Eureka No. 36	Somerset	Killed by a fall of rock. It was a regular bell or horse back. It was a pure accident as the roof sounded solid just before it fell.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1903 June 18	MYDOCK, ALEXANDER	Miner	27	Married	3	Polish	Eureka No. 30	...	Killed by fall of roof, all from neglect of his and his partner's. They had been warned and told by the assistant foreman to put up more props, but did not do so.
1903 July 25	HARWART, THOMAS	Loader	35	Married	3	Hungarian	Eureka No. 35	...	Fatally injured by a fall of rock. He was loading a car when a large piece of rock broke and rolled to the car and caught him. It was a pure accident as the break in the roof was not visible.
1903 Aug. 17	POLLOCK, CARROLL	Miner	25	Single	...	Slavonian	Eureka No. 32	Somerset	Fatally injured by a fall of rock which should have been secured. He was undermining the coal when the rock fell on him.
1903 Aug. 24	FASHAND, RAPHO	Miner	17	Single	...	Italian	Eureka No. 34	Somerset	Took an empty car out of a room, and got in it to ride out. At the bottom of the heading the car ran into a full trip going past the mouth of his heading and he was knocked out of the car and killed instantly.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1903 Sept. 18	GABO, LEWIS	Miner	17	Single	...	Magyar	Eureka No. 34	Somerset	Killed by a fall of rock which the cutter who had mined the coal had told Gabo to prop up, as it was nearly down, but he did not put any props up.
1903 Oct. 24	STEVANS, BEN.	Spragger	22	Single	...	American	Eureka No. 35	Somerset	Was crushed to death on a loaded car which ran in under the roof. The motor was pushing back ten or twelve cars to hitch to the car out of the heading face, and it is supposed he failed at first to hitch and kept trying until cars ran under the top and caught him.
1903 Nov. 4	TIMCO, MIKE	Miner	28	Married	2	Slavonian	Eureka No. 37	Somerset	Stepped out of the road of an empty trip in the mine, where there is a double track, and instead of getting to the side until trip passed he stood on the other track and was run over by the motor with a loaded trip coming out. There was a space of six feet on the side where he was struck.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1903 Nov. 4	RESOR, PETER	Miner	36	Married	4	Polish	Eureka No. 30	Somerset	Fatally injured by a fall of roof. It was purely an accident, there being a regular pot hole in the roof that was not visible.
1903 Dec. 2	LUCA, JOHN	Loader	18	Single	...	Slavonian	Eureka No. 32	Somerset	Was riding in the mine to his work and jumped out of the car, while trip was running about three miles an hour, and fell back under the cars, five of which ran over him and killed him.
1903 Dec. 7	ADAMOSKEY, JOSEPH	Miner	35	Married	3	Polish	Eureka No. 30	Somerset	Was going out the mine in the evening, and met an empty trip coming in. Instead of getting into man hole until trip passed he stepped on to loaded trip track and the motor and part of trip ran over him; his partner escaped without injury.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1904 Jan. 20	GAUCH, ALEX.	Miner	23	Single	...	Hungarian	Eureka No. 36	Somerset	Killed by electricity. He went under trolley wire to load up some loose coal on the heading, and put his neck against the wire.
1904 Feb. 9	SMITHKO, JOHN	Miner	23	Married	...	Slavonian	Eureka No. 35	Somerset	Killed by fall of rock. He was robbing some coal off the corner on the neck of his room to finish loading a car.
1904 Feb. 11	KORAN, VICTOR	Miner	22	Single	...	Slavonian	Yellow Run Shaft, Dunlo	Cambria	Killed by fall of rock. The mine foreman had told him to put up some props, but he did not do so.
1904 Mar. 21	BORASH, STEVE	Miner	25	Single	...	Polish	Eureka No. 32	Somerset	Badly crushed by fall of coal. He lay down under a large piece of coal hanging back over him to mine under it, and it fell on him.
1904 May 11	ADAMEHICK, JOSEPH	Miner	18	Slavonian	Eureka No. 35	Somerset	Fatally injured by being caught between the motor and cars.
1904 July 29	ROSELESKI, VIDA	Miner	35	Married	3	Polish	Eureka No. 37	Cambria	Crushed by electric motor and mine cars. He was walking on the hauling road and was caught by trip.
1904 Aug. 4	DRINCH, SAM	Tracklayer	28	Married	2	Italian	Eureka No. 34	Somerset	Crushed by fall of rock. Rock fell from a large fault

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1904 Aug. 13	TINKO, JOHN	Miner	27	Single	...	Slavonian	Eureka No. 35	Somerset	Fatally injured by fall of rock. A piece of rock fell out of the roof between two slips and caught him.
1904 Aug. 29	STELLA, MARTIN	Miner	35	Married	3	Hungarian	Eureka No. 37	Cambria	Caught between two cars and squeezed to death.
1904 Oct. 1	BOLOCK, STEVE	Miner	28	Married	2	Hungarian	Eureka No. 34	Somerset	Killed by fall of roof. He rushed into his place when it was falling in, to take out a few tools. His lamp went out and the roof fell on him.
1904 Dec. 17	YUCAS, ANTON	Miner	32	Single	...	Slavonian	Eureka No. 35	Somerset	Was cleaning out an old gob to get into a cut through and the roof fell on him.
1905 Jan. 26	ASHLEY, EDWARD H.	Engineer	18	Single	...	American	Yellow Run Shaft, Dunlo	Cambria	Instantly killed by the bursting of fly wheel of his engine, a piece of which struck him on the head. It was an underground hauling engine.
1905 Jan. 31	DEMETER, LENGER	Miner	34	Married	1	Russian	Eureka No. 32	Somerset	Instantly killed. Struck by a motor when coming out of the mine.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1905 Mar. 22	HORATSKI, JOHN	Loader	38	Married	3	Slavonian	Eureka No. 33	Somerset	Killed by an electric shock. Ran against trolley wire in the mine.
1905 April 4	MITCHELL, CHARLIE	Miner	26	Single	...	Polish	Eureka No. 34	Somerset	Fatally injured by fall of rock.
1905 April 6	LEECH, MIKE	Miner	24	Single	...	Hungarian	Eureka No. 36	Somerset	Fatally injured by fall of draw slate.
1905 April 9	PACHINA, JOE	Miner	36	Married	...	Hungarian	Eureka No. 36	Somerset	Fatally injured. Run over by a mine car.
1905 April 26	KATCHMER, JOHN	Miner	31	Married	1	Slavonian	Eureka No. 32	Somerset	Killed by coming in contact with underground trolley wire.
1905 June 27	SOPKI, ANDY	Miner	46	Married	3	Slavonian	Eureka No. 32	Somerset	Instantly killed by fall of rock.
1905 July 5	SHROVITS, JOHN	Miner	31	Single	...	Polish	Eureka No. 39, Upper	Somerset	Fatally injured by fall of rock.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1905 July 25	ROSERVITZ, LUDWIG	Miner	30	Married	2	Austrian	Eureka No. 30	Somerset	Killed by fall of coal. He neglected to put sprags under it.
1905 Aug. 6	SLAVIK, JOE	Track cleaner	58	Married	...	Slavonian	Eureka No. 36	Somerset	Fatally injured. Run over by a loaded mine car.
1905 Oct. 10	BORADON-CHECK, JOHN	Loader	19	Single	...	Austrian	Eureka No. 33	Somerset	Killed by the falling out of a pot hole in the roof.
1905 Nov. 2	WASER, ANDY	Miner	40	Married	4	Slavonian	Eureka No. 31	Somerset	Fatally injured by fall of coal. He neglected to sprag the coal.
1905 Nov. 13	COWOOD, JOHN	Miner	27	Married	...	Polish	Eureka No. 34	Somerset	Fatally injured by fall of rock.
1905 Nov. 15	NAVINSKI, ALEX	Track cleaner	52	Married	2	Polish	Eureka No. 36	Somerset	Fatally injured. Run over by mine cars.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Jan. 15	COLBERT, WILLIAM	Loader	40	Married	4	American	Eureka No. 30	Somerset	Killed by a fall of rock. Colbert...was badly crushed by a fall of roof. The Coal Inspector had just been in his place and noticed a small break in the roof, and warned him of the danger. Colbert said he would take the roof down, but he failed to do so and it fell and caught him.
1906 Jan. 17	GALASH, ANDY	Miner	20	Single	...	Slavonian	Eureka No. 31	Somerset	Killed instantly by a fall of roof. He was cutting with a machine. Before he started the contractor examined the roof carefully and found the top all right except in one place, where he found a thin piece of slate loose, which he secured with a prop. Galash then started to cut, and in less than five minutes a large rock fell out of the roof in the shape of a bell, and caught him.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Aug. 6	STOTLER, LEMON	Driver	21	Single	...	American	Eureka No. 33	Somerset	Fatally injured by mine cars. Stotler...was killed by a loaded car running over him. His motor was pulling a trip into one of the cross headings, and he was standing on the main waiting for the end of the trip to pass, when a loaded car came down the main heading and struck him. Some one had let the car run away from a heading above, having failed to sprag it.
1906 Sept. 14	COTTO, JOHN	Miner	21	Single	...	Slavonian	Yellow Run Shaft, Dunlo	Cambria	Instantly killed by a fall of roof.
1906 Sept. 19	MABRINA, PETE	Miner	25	Single	...	Italian	Eureka No. 34	Somerset	Killed by a mine car. Mabrina...was killed by being struck by a mine car. He was running a load down his room and lost control of the car and it went out on the heading, where a motor was passing with a loaded trip. The car ran into the motor and was knocked around, and Mabrina was thrown under the loaded cars and killed instantly.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Sept. 24	BERKEY, H. A.	Scraper	23	Single	...	American	Eureka No. 33	Somerset	<p>Killed by a fall of roof. H. A. Berkey, American scraper; John Shattack, Slavonian, loader, and Steve Mizurich, Slavonian, loader, Eureka No. 33 mine, were killed almost instantly by a large fall of rock in a room neck that had just been turned off the heading, not having fully widened out yet. There was from twelve to eighteen inches of the roof down that was to the left, and the two loaders were clearing up the place to drop this rock, when the scraper came in to see when they wanted their place cut. Just then the whole mass fell and caught the three men under it.</p>

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Sept. 24	SATTACK, JOHN	Loader	38	Married	1	Slavonian	Eureka No. 33	Somerset	Killed by a fall of rock. H. A. Berkey, American scraper; John Shattack, Slavonian, loader, and Steve Mizurich, Slavonian, loader, Eureka No. 33 mine, were killed almost instantly by a large fall of rock in a room neck that had just been turned off the heading, not having fully widened out yet. There was from twelve to eighteen inches of the roof down that was to the left, and the two loaders were clearing up the place to drop this rock, when the scraper came in to see when they wanted their place cut. Just then the whole mass fell and caught the three men under it.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Sept. 24	MIZURICH, STEVE	Loader	35	Married	0	Slavonian	Eureka No. 33	Somerset	Killed by a fall of rock. H. A. Berkey, American scraper; John Shattack, Slavonian, loader, and Steve Mizurich, Slavonian, loader, Eureka No. 33 mine, were killed almost instantly by a large fall of rock in a room neck that had just been turned off the heading, not having fully widened out yet. There was from twelve to eighteen inches of the roof down that was to the left, and the two loaders were clearing up the place to drop this rock, when the scraper came in to see when they wanted their place cut. Just then the whole mass fell and caught the three men under it.
1906 Oct. 12	HONER, JOHN VICTOR	Miner	35	Married	1	English	Eureka No. 30	Somerset	Killed by a fall of rock. He was drawing heading stumps, and had neglected to put up some props. As the roof was bad the place required a great deal of timber to keep it safe and there was sufficient timber on hand for that purpose.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Oct. 15	CRASKI, PETER	Loader	32	Married	4	Polish	Eureka No. 36	Somerset	Squeezed to death between mine car and rib. He was pushing an empty mine car in his room. The motor that was standing above his switch started down the grade, and struck the end of the car he had hold of and knocked it around against the rib, and he was caught between the mine car and the coal.
1906 Oct. 27	HOFFMAN, STINELY	Roadman	27	Single	...	Polish	Eureka No. 40	Cambria	Killed by coming in contact with electric trolley wire in the mine. At the point he touched the wire it is six feet off the rail, but between the two tracks at that point there was a big pile of rails piled up a foot higher than the track rails, and there is no doubt that Hoffman was on this pile of rails when he touched the trolley wire, as he was not over 5 feet 8 inches in height.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1906 Nov. 27	HADKISH, MIKE	Miner	41	Married	5	Slavonian	Eureka No. 37	Cambria	Killed by coming in contact with electric trolley wire in the mine. He left his regular working place and came back about 100 feet along the heading to take a cut out of a stump of coal, where the wire was right against the car he was loading. It was foolhardy for him to attempt to work at that point, as it was almost impossible for him not to get against the wire in loading his car.
1906 Nov. 29	BENNET, LEWIS	Miner	22	Married	...	Hungarian	Eureka No. 36	Somerset	Killed by a fall of rock. He was selected as a careful person to take a skip off the side of a heading, where it was supposed the roof on the sides might be dangerous, but he neglected to secure a bad piece of rock, as he was told to do so by the Assistant Foreman, and it fell on him

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1907 Jan. 4	GILLMORE, ANDA	Pipe fitter	22	Single	...	Slavonian	Eureka No. 34	Somerset	Killed by electric trolley wire in the mine. He neglected to stoop under the wire. He had to go under the wire to get into a crosscut to clean and had to let off some water so that he could work at a pipe. After completing the work he started out and forgetting about the wire, ran into it. The shock from the wire killed him.
1907 Feb. 7	FUNKENHOUSER, JOHN	Miner	31	Married	...	Hungarian	Eureka No. 30	Somerset	Killed by an electric shock. He was carrying a piece of steel rail and got one end of it between the wire and the roof, and by the rail coming in contact with the wire he was electrocuted.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1907 April 8	BENKO, JOE	Miner	36	Married	4	Hungarian	Eureka No. 36	Somerset	Killed by fall of rock that his partner wanted him to put post under. Benko...had his neck broken by fall of rock. He was drawing stumps and had taken some coal out from under a piece of rock that he knew was loose. His partner told him that he had better put a prop under it and he said that he would do so as soon as he loaded his car, but before that was done the rock fell and killed him.
1907 April 30	PRUSEK, JULOCK	Spragger	21	Single	...	Slavonian	Eureka No. 35	Somerset	Killed by mine cars on main hauling road. In some way or other he fell off the front end of the empty trip and was run over by the cars.
1907 June 17	MAHA, WASSAL	Miner	26	Single	...	Slavonian	Eureka No. 37	Cambria	Killed by fall of rock. Place was poorly posted. He had put a shot in the roof to bring down the bony, and after firing he went in through the smoke to see the effect of the shot. The roof above the bony had been loosened and it fell on him. The place was not well posted.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1907 June 25	SHOULTIS, ANDY	Scraper	43	Married	6	Hungarian	Eureka No. 39, Upper	Somerset	Killed by fall of coal and rock while engaged scraping under a puncher mining machine. He was taking coal off a corner preparatory to putting a long switch in the entry, when the corner of coal and rock, the thickness that it had been previously blasted at this point, fell on him.
1907 Aug. 9	ZAUER, PASIA	Miner	25	Single	...	Italian	Eureka No. 31	Somerset	Fatally injured by mine cars. He was in an empty car on the trip that hauls the men out of the mine from their work, and the motorman of the man trip was waiting for a trip of loaded cars to pass out ahead. When the loaded trip came along he attempted to jump on and was thrown under, getting one foot cut off and part of the other one, besides being injured otherwise. He died from his injuries in the hospital at Windber, August 23.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1907 Aug. 17	KONKULLA, STEVE	Miner	26	Married	...	Hungarian	Eureka No. 36	Somerset	Killed by shock from electric trolley wire on the heading near his working place. He stood on the heading and when standing erect the back of his neck touched the wire.
1907 Sept. 24	PHILLIP, GEORGE	Loader	24	Single	...	Polish	Eureka No. 40	Cambria	Killed by electric shock. He was passing a trip of empty cars in the mine on the trolley side, with drills on his shoulder. He was going to the mine with some drills on his shoulder, and there was a trip of empty cars on the road. He started to walk on the trolley side of the cars and it is supposed that the drills touched the wire.
1907 Nov. 21	STOCK, JOE	Miner	22	Single	...	Polish	Eureka No. 33	Somerset	Killed by fall of rock. The place was not well posted. He had neglected to properly post the place. An additional post or two would have held up the roof and prevented this accident.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1907 Dec. 31	POPLO, LOUIS	Rock dumper	23	Married	1	Italian	Eureka No. 30	Somerset	Killed instantly by the rock car. He and his partner were preparing to dump the car sideways, and had loosened the chain that prevents the car from dumping and afterward moved the car forward, and while in the act of spragging or blocking the car to stop it, it dumped and caught his head between the end of the car and the rail, killing him instantly. Outside.
1908 Jan. 22	HUNGARDEN, MIKE	Miner	38	Married	3	Slavonian	Eureka No. 36	Somerset	Killed by fall of coal at face of room while undermining along a smooth slip without sprags.
1908 Jan. 23	SKIBA, JOSEPH	Miner	37	Married	...	Polish	Eureka No. 38	Somerset	Fatally injured. He was standing in the motor barn when an electric locomotive came along, and as he attempted to jump on it he was caught between it and the door jam. Outside.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1908 Mar. 4	PETRONA, PETE	Miner	22	Single	...	Italian	Eureka No. 41	Somerset	Instantly killed by fall of rock at face of room. The place was fairly well posted, but an unseen slip caused the fall.
1908 Mar. 6	WARGO, FRANK	Miner	20	Single	...	Hungarian	Eureka No. 41	Somerset	Killed by fall of rock at face of room. He was loading a car after firing a shot, when a horse-back in the roof that had been loosened by the shot fell with the coal. The place was well posted.
1908 Mar. 16	YARNISH, GEORGE	Miner	30	Married	1	Hungarian	Eureka No. 39, Upper	Somerset	Instantly killed. He had helped the spragger switch a loaded car into No. 9 room off No. 1 south entry. He was sitting at a corner of the room pillar when an electric locomotive that was coming along jumped the track at the frog and caught him between it and the pillar.
1908 Mar. 17	LUNDEL, MIKE	Road cleaner	19	Single	...	Polish	Eureka No. 37	Cambria	Instantly killed by derailed truck between pit mouth and tipple. He was riding on the truck when the motorman saw another motor approaching, and in his effort to stop the truck, it was derailed and turned over.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1908 April 5	ROBISH, FRANK	Miner	18	Single	...	Polish	Eureka No. 34	Somerset	Instantly killed. The trip of cars on which he was riding became uncoupled, and when the rear end coupled up to the front cars again, the car on which he was riding reared up against the roof and crushed him between the roof and the car.
1908 April 29	HUDOCK, GEORGE	Miner	25	Married	1	Slavonian	Eureka No. 41	Somerset	Fatally injured by loaded car on main entry. He was walking on a loaded track when a runaway car caught him.
1908 July 1	CATS, JOE	Loader	43	Married	4	Polish	Eureka No. 36	Somerset	Instantly killed by fall of rock. There was no coal in his own room so he went out on the heading, and when he started to dig along the rib, the rock fell on him.
1908 Aug. 2	CARDEY, JOSEPH	Miner	32	Single	...	Hungarian	Eureka No. 39, Upper	Somerset	Instantly killed while pushing a loaded car out of his room. He did not look to see if the entry track was clear, but pushed ahead, striking a loaded trip of cars which knocked the rear end of his car against the corner of the room pillar, and he was caught between the car and the pillar.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1908 Aug. 6	TOAT, JOHN	Miner	42	Married	6	Hungarian	Eureka No. 36	Somerset	Squeezed by mine cars. He opened his switch and a trip of cars ran into his room, squeezing him between cars and rib.
1908 Sept. 18	SEBASTIAN, STEVE	Timberman	28	Single	...	Hungarian	Eureka No. 37	Cambria	Instantly killed by fall of rock at face of west main drift. He was setting false timbers to secure the roof, and while he was setting the last timber, the rock and timber gave way.
1908 Sept. 29	SORB, JOSEPH	Miner	21	Single	...	Hungarian	Eureka No. 30	Somerset	Fatally injured by fall of coal. He was drawing a room pillar, and while undermining a stump it fell on him, injuring him internally.
1908 Oct. 20	BROSKO, BROWNIE	Miner	27	Married	...	Polish	Eureka No. 30	Somerset	Instantly killed by fall of rock at face of entry. He had just finished putting in a mining with a puncher machine and was sitting on the machine board, when the rock fell.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1908 Nov. 3	MCHENRY, JOHN	Road cleaner	71	Married	...	Irish	Eureka No. 31	Somerset	Killed by an electric locomotive. He was cleaning the road, but as there was a trip of empty cars passing in on the empty track he did not hear the trip approaching on the loaded track, and he was struck by the locomotive before he could get out of the way.
1908 Nov. 14	SCHRUM, W. L.	Night foreman	35	Married	...	American	Eureka No. 40	Cambria	Killed by mine cars. While running a motor along the main entry, he ran into a trip of empty cars, standing on the entry, and one of the cars ran over him. It was not his duty to run the motor.
1909 Jan. 15	SHAFFER, CHRIST C.	Miner	27	Married	...	American	Eureka No. 34	Somerset	Instantly killed. Run over by electric motor while standing on haulage road.
1909 Feb. 2	CONE, JOHN	Miner	35	Married	3	Polish	Eureka No. 36	Somerset	Fatally injured by fall of slate at face of working place.
1909 Feb. 17	TOBBIAS, MICHAEL	Miner	23	Single	...	Italian	Eureka No. 31	Somerset	Killed by fall of slate while drawing entry stumps. He had failed to set posts to secure the place.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1909 Feb. 19	ROSS, MIKE	Miner	19	Single	...	Italian	Eureka No. 41	Somerset	Fatally injured by fall of roof at face of pillar work while removing his tools to a place of safety.
1909 Mar. 9	MOCKO, OGNATS	Miner	23	Single	...	Polish	Eureka No. 30	Somerset	Killed by fall of slate while drawing entry stumps.
1909 Mar. 13	DOWEN, JR., ENOCH	Pipeman	27	Married	2	English	Eureka No. 31	Somerset	Killed by shock from an electric wire charged with 500 volts while repairing pipes under an electric wire. In some way he got the back of his neck against the wire.
1909 April 9	GIBSON, WILLIAM	Roadman	22	Single	...	American	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.
1909 April 9	KOWATS, JOSEPH	Company man	30	Single	...	Polish	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.
1909 April 9	MEYERNAK, PAUL	Company man	30	Single	...	Polish	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	Count	Nature and Cause of Accident in Brief
1909 April 9	KATOPITZ, METRO	Company man	26	Single	...	Polish	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.
1909 April 9	NEMIS, STEVE	Company man	26	Married	1	Polish	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.
1909 April 9	CUSTER, ARTHUR	Miner	32	Married	4	American	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.
1909 April 9	GIBSON, MICHAEL	Company man	58	Married	3	American	Eureka No. 37, Upper	Cambria	Killed instantly while blasting rock in fourth right heading by an explosion caused by an overcharged dynamite blast, which in turn ignited the dust.
1909 April 16	WASHKO, THOMAS	Miner	17	Single	...	American	Eureka No. 30	Somerset	Killed by fall of coal while undermining in heading stumps. He failed to support the roof.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1909 May 20	SACKASH, ANDREW	Miner	20	Single	...	Hungarian	Eureka No. 35	Somerset	Killed by an electric shock from contact with live trolley wire, while shifting his car on the heading.
1909 June 21	KEMOCK, FRANK	Miner	25	Married	1	Slavonian	Eureka No. 36	Somerset	Instantly killed. Crushed between roller bar of mine wagon and roof on haulage road.
1909 July 13	KATONA, ALEX	Miner	32	Single	...	Hungarian	Eureka No. 37	Cambria	Instantly killed by an electric shock from contact with live trolley wire on haulage road.
1909 Aug. 28	PHILLIPS, THOMAS	Runner	32	Single	...	American	Eureka No. 36	Somerset	Instantly killed. Crushed between electric motor and mine cars.
1909 Sept. 7	LUTZ, JOHN	Miner	20	Single	...	Hungarian	Eureka No. 37	Cambria	Fatally injured by fall of slate while loading coal at face of working place.
1909 Sept. 13	LUCKET, ANDY	Miner	22	Single	...	Slavonian	Eureka No. 31	Somerset	Killed instantly by shock from an electric wire charged with 500 volts. He was pushing his mine car into his room, and while doing so raised his head, striking the wire.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1909 Sept. 28	FALKO, EMREY	Miner	48	Married	4	Hungarian	Eureka No. 35	Somerset	Fatally injured. He struck his head against the roof in his working place.
1909 Oct. 18	HYDOCK, GAB	Miner	26	Single	...	Hungarian	Eureka No. 36	Somerset	Killed instantly by fall of slate while loading coal at face of room.
1909 Nov. 12	MONER, FRANK	Miner	40	Married	2	Hungarian	Eureka No. 40	Cambria	Fatally injured by being crushed between mine cars and coal rib on haulage road.
1910 Feb. 23	COLINSKI, MIKE	Miner	38	Single	...	Polish	Eureka No. 37, Upper	Cambria	Fatally injured by fall of bone-coal at face of room.
1910 April 2	WINOSKI, MICHAEL	Miner	39	Married	1	Slavonian	Eureka No. 30	Somerset	Killed by coming in contact with electric wire while taking out heading stumps.
1910 April 4	LARATO, TONY	Miner	29	Married	2	Italian	Eureka No. 34	Somerset	Killed by fall of roof in pillar work.
1910 May 23	BARTISH, JOHN	Miner	22	Single	...	Hungarian	Eureka No. 36	Somerset	Killed by fall of roof in pillar work.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1910 May 27	VIDOCK, ADAM	Company man	45	Married	...	Polish	Eureka No. 35	Somerset	Instantly killed. Crushed under mine cars on entry.
1910 June 1	RONACK, JOHN	Company man	24	Married	2	Slavonian	Eureka No. 35	Somerset	Killed by fall of slate on entry.
1910 June 2	SPESOCK, JOHN	Miner	45	Married	4	Hungarian	Eureka No. 36	Somerset	Instantly killed. Crushed under mine cars on entry.
1910 June 2	LATCHNER, JOE	Miner	20	Single	...	Hungarian	Eureka No. 36	Somerset	Instantly killed. Crushed under mine cars on entry.
1910 June 23	POLINSKI, FRANK	Machine runner	28	Married	1	Slavonian	Eureka No. 35	Somerset	Killed by runaway trip of mine cars at face of entry
1910 June 27	STIFNEY, ANDY	Runner	22	Married	1	Slavonian	Eureka No. 36	Somerset	Fatally injured. Caught between electric motor and door frame on entry.
1910 June 28	KOVATZ, JOE	Miner	42	Married	...	Hungarian	Eureka No. 37	Cambria	Instantly killed by fall of slate at face of entry.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1910 July 21	SHISMACK, JOHN	Miner	32	Single	...	Slavonian	Eureka No. 35	Somerset	Fatally injured. Crushed under electric motor on entry.
1910 July 29	TOAT, MIKE	Miner	20	Single	...	Hungarian	Eureka No. 36	Somerset	Killed by fall of roof in pillar work.
1910 Aug. 24	SABATOLA, JOHN	Company man	32	Married	3	Slavonian	Eureka No. 35	Somerset	Instantly killed. Crushed under electric motor on entry.
1910 Aug. 29	HOLSINGER, DANIEL	Engineer	42	Married	6	American	Eureka No. 35	Somerset	Killed by contact with 6,000 volt electric circuit in sub-station. Outside.
1910 Sept. 10	VARGO, CARL	Miner	18	Single	...	Hungarian	Eureka No. 37	Cambria	Instantly killed. Crushed under electric motor on entry.
1910 Oct. 6	YOMMANIC, LOUIS	Miner	27	Married	1	Polish	Eureka No. 36	Somerset	Fatally injured by fall of coal at face of room.
1910 Oct. 20	COLSER, JOSEPH	Loader	34	Married	3	Magyar	Eureka No. 39, Upper	Somerset	Killed instantly by fall of slate on heading close to place where he was taking out pillars.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1910 Dec. 3	KUNKLE, WILLIAM	Company man	22	Single	...	American	Eureka No. 40	Cambria	Killed by contact with 500 volt electric circuit on entry.
1911 Jan. 10	BIGI, GOTLIB	Miner	46	Married	...	German	Eureka No. 37	Cambria	Instantly killed by fall of coal while undermining at face of his room. He neglected to set sprags under the coal.
1911 Jan. 19	NARNET, JOE	Miner	24	Married	3	Hungarian	Eureka No. 36	Somerset	Killed by coming in contact with the exposed end of an insulated wire while running a car out of his room.
1911 Feb. 17	KISH, STINY	Rockman	25	Single	...	Slavonian	Eureka No. 37	Cambria	Instantly killed by runaway cars while standing on the heading waiting for the trip.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1911 Mar. 16	FELOE, FELIX	Miner	37	Married	3	Polish	Eureka No. 40	Cambria	Fatally injured by being run over by car on cross heading. He had pushed two cars out of his room and when the second car struck the first one it ran back and caught him. Died a few days later.
1911 Mar. 24	SEECOR, JOHN	Miner	25	Single	...	Slavonian	Eureka No. 31	Somerset	Instantly killed by fall of roof while working at the face. He did not have the place properly timbered.
1911 April 1	DOCHEK, MICHAEL	Miner	22	Single	...	Slavonian	Eureka No. 34	Somerset	Killed by fall of roof while adjusting the end gate of the car at face of pillar workings.
1911 April 7	LODER, CASPER	Miner	23	Single	...	Slavonian	Eureka No. 36	Somerset	Fatally injured by fall of rock while taking out stumps on the heading. Died a few days later in hospital.
1911 May 11	GASPAR, JOHN	Rockman	40	Married	3	Slavonian	Eureka No. 42	Cambria	Fatally injured by being struck in the stomach by a bar that he was using to pull down some rock. The rock struck the bar and caused it to spring and strike him. Died two days later.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1911 June 2	CONATCH, STEVE	Miner	36	Married	3	Hungarian	Eureka No. 36	Somerset	Fatally injured by fall of rock while mining at face of pillar work.
1911 June 3	ORRIS, GUS	Loader	21	Single	...	Hungarian	Eureka No. 37	Cambria	Instantly killed by coming to contact with live wire while pushing a wagon down the heading.
1911 July 31	LEAR, JOE O.	Miner	19	Single	...	Slavonian	Eureka No. 31	Somerset	Instantly killed by fall of coal while undermining in pillar work.
1911 Aug. 26	GARETTA, DAN	Spragger	24	Single	...	Italian	Eureka No. 36	Somerset	Fatally injured by being squeezed between rib and moving motor. He got off of motor to open door on the heading.
1911 Sept. 8	WISE, D. W.	Miner	39	Married	2	American	Eureka No. 40	Cambria	Instantly killed while trying to get on some loaded wagons that he and motorman had been gathering in the pillar workings by coming in contact with the electric wire in pillar workings. The wire was unguarded and less than six and one-half feet above the rail.
1911 Sept. 27	SMOUSE, WILSON	Motorman	32	Married	5	American	Eureka No. 42	Cambria	Killed by coming in contact with the electric wire while turning the trolley pole on the heading.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1911 Oct. 31	CRESSWELL, W. S.	Laborer	70	Married	1	American	Eureka No. 36	Somerset	Fatally injured by being struck by loaded car while cleaning the track. After the trip had passed to the tippel he stepped back on the track and the trip was pushed back and struck him. Died the same evening in the hospital. Outside.
1911 Dec. 15	ESWAK, ANDREW	Miner	38	Married	4	Hungarian	Eureka No. 42	Cambria	Fatally injured by fall of rock while taking off some coal on rib side of heading in pillar workings. He had been warned by the assistant mine foreman not to work in the place on account of the dangerous conditions of the roof. Died a few days later in the hospital.
1912 Jan. 25	YONETES, RALPH	Repairman	22	Single	...	Italian	Eureka No. 40	Cambria	Fatally injured by fall of rock on heading while cleaning along the side of the road. Died the same evening.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1912 Feb. 14	GROSECK, JOSEPH	Miner	35	Married	1	Slavonian	Eureka No. 37	Cambria	Killed by fall of rock while loading a wagon in pillar work. He and his partner thought they could finish the place without setting any more props.
1912 Mar. 5	HOLSICK, ANDY	Miner	40	Married	3	Polish	Eureka No. 31	Somerset	Killed by fall of roof while taking out a pillar close to a clay vein and some dangerous top. He tried to pull the dangerous piece down but failed and, after firing a shot close to the place he began to load the coal, when the roof fell on him.
1912 Mar. 6	MOTTS, GEORGE	Miner	25	Single	...	Hungarian	Eureka No. 42	Cambria	Instantly killed by fall of coal while lying on his side mining out the coal sprags or stumps in the room.
1912 Mar. 19	BOSNOK, LOUIS	Miner	25	Married	1	Hungarian	Eureka No. 37, Upper	Cambria	Fatally injured by being struck on the side by the handles of a Pneumelectric mining machine that he was using in heading. Died in a few days.
1912 Apr. 30	LUCAS, JOHN	Miner	26	Single	...	Polish	Eureka No. 30	Somerset	Instantly killed by being struck on the head by fall of roof in pillar workings. He neglected to set some posts.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1912 July 8	PEDOR, STEPHEN	Spragger	22	Single	...	Hungarian	Eureka No. 42	Cambria	Fatally injured by being struck by a mine wagon on heading. The wagon had been derailed at the switch close to where he was standing.
1912 Sept. 2	REPASKEY, STEVE	Miner	30	Married	3	Slavonian	Eureka No. 39	Somerset	Instantly killed by fall of rock while loading a wagon and starting a room neck.
1912 Sept. 12	KELLEY, RICHARD	Miner	70	Married	...	English	Eureka No. 35, Upper	Somerset	Instantly killed by fall of coal while undermining it. He neglected to use sprags while mining in the pillar.
1912 Sept. 27	SANTY, ROBERT	Miner	27	Married	...	Hungarian	Eureka No. 36	Somerset	Instantly killed by being struck by a motor on heading. He stepped out of a shelter hole in front of the moving motor.
1912 Oct. 14	BOBASH, GEORGE	Miner	24	Married	1	Slavonian	Eureka No. 35	Somerset	Instantly killed by fall of slate while going up the heading in his working place.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1913 Jan. 1	SELVIS, JOHN	Miner	48	Married	...	Hungarian	Eureka No. 36	Somerset	Instantly killed on heading by coming in contact with an electric wire. While loading coal from the side of road the back of his head came in contact with the trolley wire.
1913 Jan. 13	GERMROTH, CHARLES F.	Laborer	47	Married	1	German	Eureka No. 39, Upper	Somerset	Instantly killed by being caught under a large rock car when it tilted endwise. Outside.
1913 Jan. 17	KORVOLSHIK, JOHN	Miner	50	Married	1	Slavonian	Eureka No. 36	Somerset	Instantly killed on heading by being caught by mine wagons while standing close to a shelter hole near his room.
1913 Jan. 31	SPASAK, ANDY	Miner	38	Married	1	Magyar	Eureka No. 35	Somerset	Instantly killed by fall of slate while pushing a loaded wagon from his place.
1913 Feb. 12	KOWASH, ALEXANDER	Loader	30	Single	...	Hungarian	Eureka No. 39, Upper	Somerset	Electrocuted by trolley wire directly above him on road.
1913 Mar. 5	RODAC, ANDY	Miner	40	Married	4	Hungarian	Eureka No. 40	Somerset	Instantly killed by fall of roof while loading a wagon in pillar workings.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1913 April 8	HANISH, JOHN	Miner	20	Single	...	Slavonian	Eureka No. 42	Cambria	Instantly killed by fall of rock while taking out heading stumps.
1913 April 10	THOMASELLI, JOSEPH	Miner	25	Married	1	Italian	Eureka No. 39	Somerset	Fatally injured by being struck by mine cars while visiting an adjoining room. Having failed to throw the switch for the heading, the cars ran into the room.
1913 June 2	SURAK, ALEXANDER	Miner	28	Miner	1	Hungarian	Eureka No. 36	Somerset	Instantly killed by fall of coal while undermining it at face of room.
1913 July 25	CHISKISKI, GEORGE	Miner	48	Married	2	Polish	Eureka No. 37	Cambria	Instantly killed while putting checks on his cars on heading. A trip of seven cars broke loose and ran into the cars he was checking.
1913 Aug. 12	PETER, THOMAS	Miner	36	Married	4	Polish	Eureka No. 37	Cambria	Fatally injured by fall of coal he failed to sprag while undermining at face of room.
1913 Aug. 19	BAKELL, JOSEPH	Miner	21	Single	...	Italian	Eureka No. 42	Cambria	Instantly killed by fall of coal and bone while undermining it at face of room. He failed to set sprags.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1913 Aug. 25	YELLOMEY, CASPER	Miner	40	Widow- er	...	Hungarian	Eureka No. 36	Somerset	Killed by fall of slate while working in pillars. He had been told to take the slate down, but failed to do so.
1913 Sept. 3	HAWIE, STEPHEN	Motorman	29	Married	...	Slavonian	Eureka No. 35	Somerset	Killed by having his head crushed between the brake-wheel of his motor and the roof on a spur of track.
1913 Sept. 12	O'ROURK, PERCY W.	Scraper	23	Single	...	American	Eureka No. 37, Upper	Cambria	Killed by fall of roof while making a machine-cut in the coal on side of heading.
1913 Dec. 25	HASLETT, THOMAS	Motorman	18	Single	...	American	Eureka No. 40	Cambria	Fatally injured on heading by being squeezed between rib and motor while running along the side to get to the front end of motor.
1914 Jan. 3	RICH, FRANK	Tippleman	36	Married	4	Italian	Eureka No. 39	Somerset	Fatally injured. His leg was squeezed between loaded mine wagons on tipple. Amputation was decided upon after a few days, and he died from the effects. Outside.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1914 Feb. 9	BARATO, GEORGE	Laborer	48	Married	5	Hungarian	Eureka No. 40	Cambria	Fatally injured by being squeezed between motor and prop on the side of main heading while on his way out of the mine. He saw the motor coming and attempted to travel to another shelter hole and was caught. Died in a few hours.
1914 April 4	ADAMSICK, JOSEPH	Miner	42	Married	...	Slavonian	Eureka No. 42	Cambria	Instantly killed by fall of coal at face of room while undermining without using sprags.
1914 June 13	SWINOR, JOHN	Spragger	22	Married	...	Slavonian	Eureka No. 42	Cambria	Instantly killed by being crushed between side of heading and empty wagons that were derailed and the wreckage piled at the place where he went for shelter at the junction of cross heading and main heading.
1914 July 22	TOKI, ANDY [Gabor (Gabriel)]	Laborer	55	Married	...	Hungarian	Eureka No. 37	Cambria	Instantly killed by fall of rock while loading a wagon of slate on the heading. It occurred along the main heading where he was helping to make room for a side track.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1914 Dec. 4	ROCK, JOHN	Miner	20	Married	1	Italian	Eureka No. 42	Cambria	Instantly killed by fall of draw slate from side of cross heading. He was taking out room pillars and would occasionally dig and load the loose coal along the sides of the heading. Instead of loading the wagons in the room pillars. While doing this he neglected to secure the top.
1915 June 3	SATILSOWSKI, JACOB	Miner	29	Single	...	Polish	Eureka No. 40	Cambria	Killed by being thrown from an empty mine car that was derailed at a parting, while being hauled out the mine.
1915 Aug. 6	BABER, JOSEPH	Miner	20	Single	...	Austrian	Eureka No. 40	Cambria	Fatally injured by fall of coal and bone while undermining coal at face of room. Died two days later.
1915 Sept. 3	BARON, JOHN	Miner	42	Married	6	Slavonian	Eureka No. 42	Cambria	Instantly killed by fall of slate while making preparations to put a prop under it.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident in Brief
1915 Oct. 9	KERULA, LESLO	Miner	53	Married	4	Austrian	Eureka No. 40	Cambria	Instantly killed by fall of coal that he was undermining at face of room.
1915 Oct. 26	BENKO, STEPHEN	Timberman	22	Single	...	Austrian	Eureka No. 35	Somerset	Instantly killed by fall of rock on main heading at a parting while making a place to set timber under rock.
1916 Feb. 24	BENNI, ALEX	Pick miner	33	Married	...	Hungarian	Eureka No. 30	Somerset	Fatally injured by fall of roof while undermining the coal close to a clay vein on the side of the heading. Died the same day in hospital.
1916 April 22	HOAGLAND, ANDREW	Wireman	45	Married	4	Swedish	Eureka No. 40	Cambria	Fatally injured. Run over by motor on main heading while repairing the trolley lines. Motors were coming in opposite directions on the double track and in getting out of the way of one he stepped in front of the other. Died the same day in hospital

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1916 May 17	FERENCE, STEVE	Rockman	35	Married	2	Hungarian	Eureka No. 42	Somerset	Instantly killed. They [FERENCE and Swetz] were going into the mine with a motor and two wagons. At a point along the main heading, Ference asked Swetz to come over on the motor and he would teach him how to run a motor. Swetz went on the motor and proceeded to run it down the heading and ran into the rear end of a trip going down the heading.
1916 May 17	SWETZ, ANDY	Rockman	19	Single	...	Hungarian	Eureka No. 42	Somerset	Instantly killed. They [FERENCE and Swetz] were going into the mine with a motor and two wagons. At a point along the main heading, Ference asked Swetz to come over on the motor and he would teach him how to run a motor. Swetz went on the motor and proceeded to run it down the heading and ran into the rear end of a trip going down the heading.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1916 Aug. 25	SELATS, NICHOLAS	Pick miner	28	Single	...	Italian	Eureka No. 40	Cambria	Fatally injured. While working at the low side of the air course some wagons that had been left standing on the heading ran down into the air course and caught him. Died the next day.
1916 Oct. 28	NULL, WILLIAM	Fireman	56	Married	2	American	Eureka No. 35	Somerset	Scalded to death. While working in front of the boilers some tubes pulled out of the drum, and the steam and hot water blew out of the fire doors, carrying hot coals with them. Outside.
1916 Oct. 30	DONNETTI, JOE	Pick miner	23	Single	...	Italian	Eureka No. 36	Somerset	Fatally injured. He had fired a charge of powder in a top rock hole at face of heading in the evening. It failed to bring down the rock and the next morning while charging the same hole with dynamite it exploded. Died in a few days in hospital.
1916 Nov. 4	HUGHES, RICHARD	Pick miner	70	Single	...	Welsh	Eureka No. 36	Somerset	Fatally injured by fall of draw slate while undermining coal in room neck. Died in hospital five days afterward.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1917 Mar. 23	SWETZ, STEVE	Miner	32	Married	...	Hungarian	Eureka No. 36	Somerset	Compound fracture of lower jaw by fall of coal while lying down mining. Died two weeks later.
1917 Mar. 26	POLINKIS, STEPHEN	Miner	33	Single	...	Hungarian	Eureka No. 37	Cambria	Fatally injured by being struck by motor. He was walking out of the mine and stepped on the track in front of trip. Died in a few hours.
1917 April 3	KOLOSSET, MIKE	Miner	36	Married	...	Slavonian	Eureka No. 31	Somerset	Killed by being run over by empty mine wagons which he was preparing to sprag. The spragger had failed to throw the proper switch.
1917 April 5	STEVE, LOUIS	Miner	38	Married	6	Hungarian	Eureka No. 37, West	Cambria	Electrocuted while attempting to move trip of cars that had stopped at a switch. He went between two cars and his head came in contact with the wire.
1917 July 12	HAGEN, FRANCIS	Motorman	19	Married	1	American	Eureka No. 36	Somerset	Fatally injured. He jumped from a trip of which he had lost control going down a heading and part of trip passed over him. Died the next day.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1917 Aug. 4	MARK, MIKE	Laborer	58	Single	...	Roumanian	Eureka No. 40	Cambria	Fatally injured. He jumped from car of runaway trip and was caught against the rib. Died the next day.
1917 Aug. 11	BONOSKI, JOHN	Miner	29	Single	...	Slavonian	Eureka No. 35	Somerset	Instantly killed by fall of slate in air course. He went back after firing a shot before he knew whether the top was safe.
1917 Sept. 14	SLAPKA, MIKE	Laborer	24	Married	1	Slavonian	Eureka No. 36	Somerset	Fatally injured. Struck by motor while lying on the track asleep on main heading. Died the next day.
1917 Sept. 29	BEST, JOHN	Laborer	34	Married	3	Slavonian	Eureka No. 36	Somerset	Instantly killed by fall of top slate while pulling out props in abandoned pillar and stump workings. They [Best and Torkarsick] used poor judgment.
1917 Sept. 29	TORKARSICK, PETER	Laborer	36	Married	4	Slavonian	Eureka No. 36	Somerset	Instantly killed by fall of top slate while pulling out props in abandoned pillar and stump workings. They [Best and Torkarsick] used poor judgment.
1917 Oct. 5	LUMADUE, HARRY	Loader	24	Married	1	American	Eureka No. 39	Somerset	Electrocuted. While loading coal at side of heading his head touched the trolley wire.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1917 Nov. 6	SARINDY, STINEY	Miner	31	Married	3	Russian	Eureka No. 30	Somerset	Fatally injured by fall of slate from which he had removed the props to lay a side-track. Died the same day.
1918 Jan. 5	WARD, JOSEPH	Motor- man's assistant	19	Single	...	American	Eureka No. 37	Cambria	Instantly killed when his head was caught between the headlight of the motor and the roof. He was riding on the motor along the main heading when the armature case dropped down, causing the motor to rise toward the roof.
1918 Feb. 27	SELIGO, JOHN	Machine miner	29	Married	...	Polish	Eureka No. 36	Somerset	Instantly killed by fall of slate in room. It is supposed that he knocked out a prop to allow machine to go into a cross-cut to cut the face and the top fell.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1918 Aug. 17	HATALLA, JOHN	Laborer	45	Married	3	Slavonian	Eureka No. 35	Somerset	Asphyxiated by fumes and smoke which were drawn into their working place from a fire of unknown origin in the No. 24 shaft at the pumping station. They [Hatalla and Kovac] suffocated before they could reach the fresh air currents in the main heading
1918 Aug. 17	KOVAC, GEORGE	Laborer	23	Married	2	Slavonian	Eureka No. 35	Somerset	Asphyxiated by fumes and smoke which were drawn into their working place from a fire of unknown origin in the No. 24 shaft at the pumping station. They [Hatalla and Kovac] suffocated before they could reach the fresh air currents in the main heading
1918 Sept. 19	PAVLOVSKY, ANDY	Motor-man's assistant	21	Single	...	Slavonian	Eureka No. 35	Somerset	Instantly killed when run over by trip of empty cars being pushed into entry. He had been riding on the front end and was stepping off when the accident happened.
1918 Sept. 25	CRAGNALE, CARMINE	Pick miner	31	Married	...	Italian	Eureka No. 42	Cambria	Instantly killed by fall of roof while loading a car of coal in room.

Berwind-White Mines: Fatal Accidents in the Windber Area, 1898-1918 (continued)

Date	Name of Person	Occupation	Age	Marital Status	Children	Nationality	Name of Colliery	County	Nature and Cause of Accident In Brief
1918 Sept. 25	SABO, STEVE	Pick miner	33	Married	...	Hungarian	Eureka No. 42	Cambria	Fatally injured by fall of draw-slate while loading car of coal. Died in November.
1918 Sept. 26	SAVAGE, JOHN	Pick Miner	19	Single	...	American	Eureka No. 40	Cambria	Electrocuted. He was operating an electric hoist and in some undetermined way came in contact with the current.
1918 Sept. 28	UHOUSE, JAMES	Pick miner	33	Married	...	Hungarian	Eureka No. 37	Cambria	Instantly killed by fall of rock while loading car of coal.
1918 Nov. 26	MALINDA, MIKE	Pick miner	32	Married	...	Hungarian	Eureka No. 40	Cambria	Instantly killed by fall of slate in pillar work.

SOURCES: Pennsylvania Department of Internal Affairs, Bureau of Mines, *Report of the Bureau of Mines of Pennsylvania*, annual reports, 1897-1902 (Harrisburg: State Printer, 1898-1903); and Pennsylvania Department of Mines, *Report of the Department of Mines of Pennsylvania*, annual reports, 1903-1918 (Harrisburg: State Printer, 1904-1919).